





NO.631
FLEETCUT
POLISHING COMPOUND

MACHINE USE GUIDE



	HEAVY NEGLECT	MODERATE NEGLECT	MILD NEGLECT
SURFACE CONDITION →			
DESIRED RESULT →	REMOVE HEAVY OXIDATION	REMOVE MODERATE OXIDATION	REMOVE MILD OXIDATION, POLISH FOR MIRROR FINISH
MACHINE CHOICE →	ROTARY 	ROTARY DA  OR 	DA 
PAD CHOICE →	WOOL CUTTING	WOOL CUTTING	FOAM OR WOOL POLISHING
AMOUNT OF PRODUCT APPLIED →	6-10 DROPS TO 10" ROTARY PAD	5-6 DROPS TO ROTARY PAD, 5-6 DROPS TO DA PAD	4-5 DROPS TO 6" DA PAD
PRESSURE APPLIED TO MACHINE →	FIRM 25-40 LBS	MODERATE 15-25 LBS	LIGHT 5-15 LBS
BUFFING CYCLE →	2-3 MINUTES 4-8 PASSES	1-2 MINUTES 4-6 PASSES	1-2 MIN 2-4 PASSES